

UNITED STATES PATENT AND TRADEMARK OFFICE

UNITED STATES DEPARTMENT OF COMMERCE United States Patent and Trademark Office Address: COMMISSIONER FOR PATENTS P.O. Box 1450 Alexandra, Virginia 22313-1450 www.uspto.gov

APPLICATION NO.	FILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO.
10/633,350	08/01/2003	Jude A. Kral	ST8724US	3716
22203	7590 12/23/2005		EXAMINER	
KUSNER & JAFFE HIGHLAND PLACE SUITE 310 6151 WILSON MILLS ROAD HIGHLAND HEIGHTS, OH 44143			SHAFFNER, FRANK C	
			ART UNIT	PAPER NUMBER
			1744	

DATE MAILED: 12/23/2005

Please find below and/or attached an Office communication concerning this application or proceeding.

		#\/				
	Application No.	Applicant(s)				
	10/633,350	KRAL ET AL.				
Office Action Summary	Examiner	Art Unit				
	Frank Shaffner	1744				
The MAILING DATE of this communication app Period for Reply	ears on the cover sheet with the o	correspondence address				
A SHORTENED STATUTORY PERIOD FOR REPLY WHICHEVER IS LONGER, FROM THE MAILING DA - Extensions of time may be available under the provisions of 37 CFR 1.13 after SIX (6) MONTHS from the mailing date of this communication. - If NO period for reply is specified above, the maximum statutory period w - Failure to reply within the set or extended period for reply will, by statute, Any reply received by the Office later than three months after the mailing earned patent term adjustment. See 37 CFR 1.704(b).	ATE OF THIS COMMUNICATION 16(a). In no event, however, may a reply be tiruly apply and will expire SIX (6) MONTHS from cause the application to become ABANDONE	N. nely filed the mailing date of this communication. (D) (35 U.S.C. § 133).				
Status						
1) Responsive to communication(s) filed on 01 Au	<u>ıgust 2003</u> .					
	action is non-final.					
·	Since this application is in condition for allowance except for formal matters, prosecution as to the merits is closed in accordance with the practice under <i>Ex parte Quayle</i> , 1935 C.D. 11, 453 O.G. 213.					
Disposition of Claims						
4)⊠ Claim(s) <u>1-9</u> is/are pending in the application.						
4a) Of the above claim(s) is/are withdrawn from consideration.						
5) Claim(s) is/are allowed.						
6)⊠ Claim(s) <u>1-9</u> is/are rejected.	⊠ Claim(s) <u>1-9</u> is/are rejected.					
7) Claim(s) 4 is/are objected to.						
8) Claim(s) are subject to restriction and/or	election requirement.					
Application Papers						
9) The specification is objected to by the Examine	r.					
10)⊠ The drawing(s) filed on <u>01 August 2003</u> is/are:	a)⊠ accepted or b)□ objected	to by the Examiner.				
Applicant may not request that any objection to the	drawing(s) be held in abeyance. Se	e 37 CFR 1.85(a).				
Replacement drawing sheet(s) including the correcti	• • • • • • • • • • • • • • • • • • • •					
11) ☐ The oath or declaration is objected to by the Ex	aminer. Note the attached Office	Action or form PTO-152.				
Priority under 35 U.S.C. § 119						
12) Acknowledgment is made of a claim for foreign a) All b) Some * c) None of:	priority under 35 U.S.C. § 119(a)-(d) or (f).				
1. Certified copies of the priority documents have been received.						
2. Certified copies of the priority documents have been received in Application No						
3. Copies of the certified copies of the prior	ity documents have been receive	ed in this National Stage				
application from the International Bureau	(PCT Rule 17.2(a)).					
* See the attached detailed Office action for a list of	of the certified copies not receive	ed.				
Attachment(s)	4) 🗆 Into-:: C	(PTO 413)				
Notice of References Cited (PTO-892) Notice of Draftsperson's Patent Drawing Review (PTO-948)	4) Interview Summary Paper No(s)/Mail D					
3) Information Disclosure Statement(s) (PTO-1449 or PTO/SB/08) Paper No(s)/Mail Date	5) Notice of Informal F 6) Other:	Patent Application (PTO-152)				

Application/Control Number: 10/633,350 Page 2

Art Unit: 1744

DETAILED ACTION

Claim Objections

1. Claim 4 is objected to because of the following informalities: in claim 4, "with type" should be "with the type". Appropriate correction is required.

Claim Rejections - 35 USC § 112

2. The following is a quotation of the second paragraph of 35 U.S.C. 112:

The specification shall conclude with one or more claims particularly pointing out and distinctly claiming the subject matter which the applicant regards as his invention.

3. Claim 7 is rejected under 35 U.S.C. 112, second paragraph, as being indefinite for failing to particularly point out and distinctly claim the subject matter which applicant regards as the invention.

Claim 7 is indefinite because it is unclear as to if the controller determines where a connection is to be made or if a connection is proper or improper. Also, it is unclear as to whether the controller determines a predetermined pressure or if this pressure is inputted into the controller.

Claim Rejections - 35 USC § 103

4. The following is a quotation of 35 U.S.C. 103(a) which forms the basis for all obviousness rejections set forth in this Office action:

(a) A patent may not be obtained though the invention is not identically disclosed or described as set forth in section 102 of this title, if the differences between the subject matter sought to be patented and the prior art are such that the subject matter as a whole would have been obvious at the time the invention was made to a person having ordinary skill in the art to which said subject matter pertains. Patentability shall not be negatived by the manner in which the invention was made.

Based on the examiner's best interpretation of the applicant's claims:

Application/Control Number: 10/633,350

Art Unit: 1744

5. Claims 1, 5, and 6 are rejected under 35 U.S.C. 103(a) as being unpatentable over Weber et al. in view of Mapson et al., and further in view of Malkin et al.

Page 3

Regarding claim 1, in U.S. Patent 5,761,069, Weber et al. teach a system for monitoring fluid circulation in a reprocessor apparatus for sterilization (Abstract, column 1 lines 7-9) where there are fluid connections (column 14 lines 57-60). The monitoring system comprises a pressure sensor for sensing a pressure and generating an electrical signal indicative of a sensed pressure (column 12 lines 24-31), and a controller (column 4 lines 55-57) responsive to the electrical signal (column 12 lines 30-31). Weber et al. teach the pressure sensed is indicative of the failed circulation pump (column 12 lines 26-29), however, Weber et al. fail to teach the importance of ensuring the connections within the reprocessing system are secure.

In U.S. Patent 6,485,684, Mapson et al. teach a reprocessing system for endoscope sterilization in which the exterior surfaces of endoscopes are sprayed with sterilant and the inner lumens are pressurized with sterilant through connected tubing (Abstract). Instruments such as endoscopes have a plurality of openings, and require that sterilant is flowed through different openings at different pressures. Additionally, some lumens do not need to be sterilized and would be damaged when contacted by fluids (column 1 lines 29-40). When improper connections are made between sterilant tubes and medical instruments, assurance that the sterilant is contacting all microorganisms in the lumens is lost (column 1 lines 49-52), leaving the instrument contaminated. Mapson et al. also teach using a leak detector in the reprocessing system to determine if the lumen is holding a preselected vacuum or positive pressure (column 4 lines 24-27). This shows the importance of having a fully pressurized system to expose all

Art Unit: 1744

microorganisms to sterilant and ensuring certain parts of instruments are not contacted by fluids.

A decrease in fluid pressure within the system would be evidenced by an improper connection.

In U.S. Patent Application Publication 2004/0091389 A1, Malkin et al. teach that in a flexible endoscope steam sterilization system, pressure tests can be run to determine the channels or lumens that are connected with the steam sterilant source (paragraph 48).

Therefore, it would have been obvious to one having ordinary skill in the art at the time the invention was made to use the pressure sensor in Weber et al.'s invention to determine if there is an improper connection between the medical instrument and the sterilant ports because an improper connection would lead to fluid pressure and sterilant losses, thereby increasing the expense to operate Weber et al.'s reprocessor apparatus. Additionally, a proper connection would have been beneficial to Weber et al.'s reprocessor because it would have further ensured that medical instrument sterilization was complete by leaving no part of the instrument contaminated as taught by Mapson et al. above, which is a concern since Malkin et al. teach the complexity of the inner parts of endoscopes (paragraph 8).

Regarding claim 5, Weber et al. teach the controller workstation comprises a keyboard (column 6 lines 26-28).

Regarding claim 6, Weber et al. additionally teach the input unit allows input of information for selecting the type of device being sterilized (column 5 line 66-column 6 line 6). Inserting a diskette and inputting information into the keyboard will allow the user to select the reprocessing unit to use based on the device being sterilized (column 7 line 62-column 8 line 31).

Art Unit: 1744

6. Claims 2-4 and 7-9 are rejected under 35 U.S.C. 103(a) as being unpatentable over Weber et al. in view of the combination of Mapson et al. and Malkin et al. as applied to claim 1 above, and further in view of Moser.

Regarding claim 2, Weber et al. additionally teach a display unit for indicating the status of various components of the reprocessing unit (column 8 line 64-column 9 line 1). However, Weber et al. fail to teach displaying the location in the reprocessor apparatus where an improper connection has been detected.

In U.S. Patent 5,279,799, Moser et al. teach a sterilization system for endoscopes in which endoscope ducts are checked for clogs. When a clogged duct is determined, the specific duct is indicated on a display field of the control unit (column 6 lines 15-18).

Therefore, it would have been obvious to one having ordinary skill in the art at the time the invention was made to display the location of an improper connection found in Weber et al.'s reprocessor apparatus on the screen display just as the clogged duct location was displayed in Moser's invention to notify the user of which connection is improper so the connection can be made proper, thereby increasing the response time for operators to make the reprocessor safe from spilled sterilant. This would have also aided in preventing the shutdown of all the reprocessors at once to correct the connection, since Weber et al. teach that all four reprocessors could be controlled and monitored simultaneously (column 8 lines 22-26).

Regarding claim 3, Malkin et al. further teach that the central processor responds with error messages, status notifications, and the like at the user interface display (paragraph 80). It would have been obvious to one having ordinary skill in the art at the time the invention was made to display corrective actions on the display screen of Weber et al.'s invention to aid

Art Unit: 1744

hospital users who are new to using the reprocessor apparatus in correcting a connection problem, which, as Malkin et al. teaches, would contribute to faster-acting sterilization (paragraph 11).

Regarding claim 4, Weber et al. teach displaying information associated with the type of medical instruments being reprocessed (column 5 lines 7-10, column 9 line 61-column 10 line 9).

Regarding claim 7, Weber et al. in view of Malkin et al. teach the controller would determine the connection of medical instruments to sterilant sources as described above. Moser discloses that a leaking endoscope will result in a pressure drop and that an endoscope with no leaks will increase pressure (column 5 lines 34-49), making a leak intrinsic to an improper connection because the pressure sensors are connected to the line entering the endoscope (column 5 lines 18-23). Therefore, it would have been obvious to one having ordinary skill in the art at the time the invention was made to conclude that a proper connection is obtained when the pressure increased in the medical instrument. Moser also teaches a predetermined pressure of 0.20 bar is reached and the controller makes the appropriate pressure reductions (column 5 lines 34-38).

Regarding claim 8, Moser teaches an alarm is triggered when there is a leak in the endoscope (column 5 lines 49-50). It would have been obvious to one having ordinary skill in the art at the time the invention was made to implement an audible alarm so that users that were not looking directly at the screen or working on other operations in the control room could be notified promptly, eliminating the consequence of being alerted too late and endangering personnel with leaking sterilant.

Application/Control Number: 10/633,350 Page 7

Art Unit: 1744

Regarding claim 9, Moser teaches that a pressure value associated with an improper connection is lower than 0.18 bar and a pressure higher than 0.18 bar is associated with a proper connection (column 5 lines 34-49).

Conclusion

7. The prior art made of record and not relied upon is considered pertinent to applicant's disclosure. In U.S. Patent 5,738,824, Pfeifer discloses a method for disinfecting surgical tools and determining the penetrability of each tool.

Application/Control Number: 10/633,350 Page 8

Art Unit: 1744

Any inquiry concerning this communication or earlier communications from the examiner should be directed to Frank Shaffner whose telephone number is (571) 272-5568. The examiner can normally be reached on Monday through Friday, 7:30 AM until 4:30 PM.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Richard Crispino can be reached on (571) 272-1226. The fax phone number for the organization where this application or proceeding is assigned is 571-273-8300.

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see http://pair-direct.uspto.gov. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free).

FS

FI

December 21, 2005

KRISANNE JASTRZAB PRIMARY EXAMINED